

Advisory Wire

REFERENCE NO: AW700-09-0769

INFORMATION TYPE: Maintenance

ATA: 09-10-00

EFFECTIVITY: Global 7500 (70006 – 79999)

SUBJECT: Towing Aircraft with a Portable Towbar

1. REFERENCES:

-Global 7500 AMP task BD700-A-J09-10-00-00AAA-174A-A Towing the aircraft with a towbar – Towing
-SGSE 09X78K-10-02 - Tow-bar Air Transportable

2. INTRODUCTION:

Bombardier received a damage report resulting from the usage of the portable towbar combined with a cabin equipped towing vehicle .

3. DESCRIPTION:

Due to the length of the portable towbar, ref. SGSE 09X78K-10-02, special attention must be given when used in conjunction with a cabin equipped towing vehicle. The ground crew must ensure that the towing vehicle provides sufficient clearance with the aircraft nose radome before reaching the attaching pin in order to avoid any contact. Proper clearance must be considered at all angles.

4. ACTION:

Future revision of Global 7500 AMP task BD700-A-J09-10-00-00AAA-174A-A Towing the aircraft with a Towbar, will be amended to include a caution in the Safety Conditions section.

Should you have any technical queries pertaining to this Advisory Wire, please contact your local [Field Service Representative](#).